ME FILE COPY



Annual Report Grant No. N00014-85-K0179 September 1, 1987 - September 30, 1988

INVESTIGATION OF MICROSTRUCTURAL FACTORS THAT CAUSE LOW FRACTURE TOUGHNESS IN SILICON CARBIDE WHISKER/AI ALLOY COMPOSITES

Submitted to:

Office of Naval Research 800 N. Quincy Street Arlington, VA 22217-5000

Attention: Dr. Steven Fishman Non-Metallic Materials Code 1131N


Submitted by:

F. E. Wawner Research Professor

R. D. Schueller Graduate Research Assistant



Report No. UVA/525398/MS89/103 October 1988



SCHOOL OF ENGINEERING AND APPLIED SCIENCE

DEPARTMENT OF MATERIALS SCIENCE

DISTRIBUTION STATEMENT A

Approved to adea, principal

UNIVERSITY OF VIRGINIA
CHARLOTTESVILLE, VIRGINIA 22901

89 1011 216

Annual Report
Grant No. N00014-85-K0179
September 1, 1987 - September 30, 1988

INVESTIGATION OF MICROSTRUCTURAL FACTORS THAT CAUSE LOW FRACTURE TOUGHNESS IN SILICON CARBIDE WHISKER/Al ALLOY COMPOSITES

Submitted to:

Office of Naval Research 800 N. Quincy Street Arlington, VA 22217-5000

Attention: Dr. Steven Fishman Non-Metallic Materials Code 1131N

Submitted by:

F. E. Wawner Research Professor

R. D. Schueller Graduate Research Assistant

Department of Materials Science
SCHOOL OF ENGINEERING AND APPLIED SCIENCE
UNIVERSITY OF VIRGINIA
CHARLOTTESVILLE, VIRGINIA

Report No. UVA/525398/MS89/103 October 1988 Copy No. ____

REPORT DOCUMENTATION PAGE							
18. REPORT SECURITY CLASSIFICATION			16. RESTRICTIVE MARKINGS				
Unclassified			None			·	
2a. SECURITY CLASSIFICATION AUTHORITY			3. DISTRIBUTION/AVAILABILITY OF REFORT Approved for public release; distribution				
2b. DECLASSIFICATION / DOWNGRADING SCHEDULE			unlimited				
4. PERFORMING	ORGANIZATI	ON REPORT NUMBE	R(S)	5. MONITORING	ORGANIZATION RE	PORT NUMB	ER(S)
UVA/5253	398/MS89/	103					
6a. NAME OF PERFORMING ORGANIZATION 6b. OFFICE SYMBOL			7a. NAME OF MONITORING ORGANIZATION				
University of Virginia ((f applicable) Dept. of Materials Science			Office of Naval Research Resident Representative				
6c. ADDRESS (C			L	7b. ADDRESS (City, State, and ZIP Code)			
Thornton		2 6006,		818 Connecticut Ave., N.W.			
Charlott	tesville,	VA 22901		Eighth Floor			
				Washington, DC 20006			
8a. NAME OF F ORGANIZAT		NSORING	8b. OFFICE SYMBOL (If applicable)	9. PROCUREMENT INSTRUMENT IDENTIFICATION NIJMBER			
Office of	of Naval	Research		N00014-85	-K0179		į
8c. ADDRESS (C	ity, State, and	ZIP Code)		10. SOURCE OF F	UNDING NUMBER	S	
800 N. (Quincy St	reet		PROGRAM	PROJECT	TASK	WORK UNIT
Arlingto	on, VA 2	2217-5000		ELEMENT NO.	NO.	NO.	ACCESSION NO.
11. TITLE (Inclu	ida Sacurity C	(lactification)			<u> </u>	·	
Investi	gation of	Microstructu	ral Factors that	Cause Low F	racture Toug	hness ir	Silicon
		Al Alloy Comp		•	•		
.12 PERSONAL	AUTHOR(S)			·			
		D. Schueller					
13a, TYPE OF I		13b. TIME C FROM09/	OVERED 01/87 TO 09/30/8	14. DATE OF REPO	RT (Year, Month, I	Day) 15. P/	AGE COUNT
16. SUPPLEMEN	NTARY NOTAL						
17.	COSATI	CODES	1 18. SUBJECT TERMS (Continue on reverse	e if necessary and	identify by	block number)
FIELD	GROUP	SUB-GROUP]		·		•
]				
			<u> </u>	·····			
19. ABSTRACT	(Continue on	reverse if necessary	and identify by block r	number)			
	J This	program deal	s with determining	ne factors th	at influence	strenet	·h
This program deals with determining factors that influence strength, ductility, fracture toughness, and elongation to failure in Sic							
whisker/Ar alloy composites. Specifically, a microstructural study is							
being made in an attempt to define extrinsic and intrinsic factors that							
	control f	racture and th	hus influence pro	perties.			
One of the more important products produced by ACMC from $\mathrm{SiC}_{G}^{O}/\mathrm{Al}$							
composites has been the rolled sheet. The response of the material to							
secondary processing and thermo-mechanical treatment is of utmost							
importance with respect to material quality. The present study							
emphasizes microstructural-mechanical property characterization of the							
rolled material.							
		ILITY OF ABSTRACT			CURITY CLASSIFIC	ATION	
UNCLASSIFIED/UNLIMITED SAME AS RPT DTIC USERS Unclassified							
•				226. TELEPHONE	(Include Area Code	22c. OFFI	CE SYMBOL
Dr. Steven Fishman							

SECURITY CLASSIFICATION OF THIS PAGE

It has been confirmed in this study that when A12124 15° SiCw is hot rolled it loses a good portion of its strength. It has been found that this loss in strength is mainly due to overaging of the precipitation hardenable matrix. Evidence shows that large Al₂Cu precipitates grow as the material is allowed to cool down after the rolling step.

It has also been confirmed that the strength of the material can be regained by subjecting it to a T6 heat treatment (1 hour at 500°C, CWC, and aged at 150°C for 8 hours). Experiments show that the strength is regained mainly because the heat treatment disperses the precipitates. However, it has been discovered that this rather long heat treatment sequence can be made much shorter due to the high dislocation density of this material. The precipitates can be dispersed by solutionizing the material at 500°C for very short periods of time (as short as 1.5 minutes) followed by cold water quenching. Likewise, it has been found that only a very simple aging process is needed to obtain peak strength. Artificial aging at 150°C is not necessary. The material need only be aged at room temperature for a time of 7 hours or more. Thus industry should be able to heat treat the rolled composite material much more efficiently and inexpensively than a T6 heat treatment would permit.

The large precipitates weaken the composite in three basic ways:

- 1) The growth of large precipitates can weaken the material by removing the small precipitates which are needed to help prevent dislocation motion, thus slip. Therefore, the shear strength of the matrix is reduced which results in a larger critical whisker length. Thus shorter whiskers are unable to carry as much load and the material is weakened.
- 2) The large precipitates also tend to create large voids in the composite which then act as crack initiation sites and also provide low energy crack paths.
- 3) Evidence shows that the precipitates tend to nucleate at dislocations near the interface. Therefore, the precipitates tend to grow around the whiskers and envelope them, thus rendering the strengthening effect of the whiskers useless.

It was shown that the A12124 matrix provided a much stronger composite than a pure aluminum matrix, at least up to a temperature of 400°C. At temperatures higher than this it appears as if precipitation strengthening offers no contribution to the strength. It has also been shown that the reinforcement itself offers no contribution to the strength at temperatures above 300°C, due to very low shear strengths in the matrix at these high temperatures. Through elevated temperature shear tests it was shown that the main reason for the drop in strength at higher temperatures was due to a rapid decrease in shear strength of the matrix.

It was also found that not only does the T6 heat treatment increase the strength of the rolled composite but it also increases the room temperature ductility. The AR material has very poor ductility because the large precipitates initiate cracks, which lead to tensile fracture, before much plastic deformation can take place. However, the ductility of the AR material increases with temperature to a maximum near 350°C, while the ductility of the T6 material decreases to a minimum at a temperature of 300°C. The precipitates are also thought to be responsible for these effects.

The extruded A12124 15% SiCw composite was much less homogeneous than the hot rolled material. Precipitates were observed to grow in linear groups along the extruded direction apparently due to variations in plastic deformation.

TABLE OF CONTENTS

		<u>Page</u>
I.	INTRODUCTION	1
II.	RESULTS AND DISCUSSION	4
	EFFECTS OF HOT ROLLING ON AL2124 15% SiCw COMPOSITES OBSERVING AND IDENTIFYING THE PRECIPITATES DISPERSION OF THE PRECIPITATES GROWTH OF PRECIPITATES UPON COOLING DETRIMENTAL EFFECTS OF LARGE PRECIPITATES LOWERING OF THE MATRIX SHEAR STRENGTH PRECIPITATES FORM CRACK INITIATION SITES AND PROVIDE LOW ENERGY CRACK PATHS	5 7 12
	NUCLEATION OF Al ₂ Cu NEAR THE WHISKER INTERFACE	
	GROWTH OF PRECIPITATES EFFECTS OF HIGH TEMPERATURE ON A1 2124-SiCw COMPOSITES EFFECTS OF TEMPERATURE ON THE STRENGTH EFFECTS OF TEMPERATURE ON DUCTILITY	27 30 30
III.	CONCLUSIONS	45
	EFFECTS OF HOT ROLLING ON AL2124-SiCw COMPOSITES WAYS IN WHICH THE PRECIPITATES WEAKEN THE COMPOSITE HIGH TEMPERATURE FRACTURE HIGH TEMPERATURE DUCTILITY OTHER OBSERVATIONS	45 46 46
IV.	FUTURE RESEARCH	48
	REFERENCES	49
	PUBLICATIONS AND PRESENTATIONS	50



Acces	sion For	
NTIS	GF. 4.8: I	1
DILC	Ta:	i' .
Unan	41 W 61 A	3
Just	Tiett soll	
!		
By		
Dist	nita ve e e	_
Ava.	101177	1.1
	Avery 15	•
Dist	1:011.	
1		
1/1		
p		
. ■	1	

SECTION I

The stigma of high cost which has inhibited the use of metal matrix composite materials for many years is slowly being removed. It roved manufacturing techniques for the reinforcements and composites, higher volume usage, and a realization that lifetime factors and efficiency improvements must be considered in an overall economic evaluation have led to increased incorporation of the materials into present day and future design concepts.

Additionally, many of the conventional metals and their alloying components (i.e., additives such as Ti, Cr, Co) are primarily imported from potentially unstable nations and have been placed on a critical materials list. For this reason, replacement of these materials may be a forced necessity in the very near future. Metals matrix composites are strongly being considered to fulfill this role.

One such materials system that has moved rapidly from its laboratory inception to commercialization is a silicon carbide whisker reinforced aluminum composite material. This material is composed of typically 15-20 volume percent whiskers in various aluminum alloy matrices and has demonstrated strength values that equal or exceed most Al alloys and a Young's modulus that is 75% higher (18x10⁶psi [124 GPa]). These properties are quite similar to those obtained for many titanium alloys and at a lighter weight, hence, specific properties for the whisker reinforced material are even more impressive. These properties along with additional advantages of being able to use conventional forming methods such as extrusion, forging, rolling, etc.

make the material attractive from an economic as well as a convenience standpoint.

The development of SiC whisker reinforced composite material has followed a logical progression in that baseline mechanical property data has been established, as well as limited microstructural characterization. As with many materials, success comes quickly in the early stages of development only to succumb to more subtle problems later on. These subtleties are overcome only by completely understanding the system. Most frequently the limitations are microstructurally related and on an atomic level. Hence, correlation of specimen history and properties with microstructural observations can lead to an understanding which could extend the range of properties for the material.

This program deals with determining factors that influence strength, ductility, fracture toughness, elongation to failure in SiC whisker/Al alloy composites. Specifically, a microstructural study is being made in an attempt to define extrinsic and intrinsic factors that control fracture and thus influence properties. The information derived will then be used make recommendations for upgrading the properties of this important materials system.

Past microstructural studies have indicated that constituent particles in the 3-5 micron size range dominate failure in the present composite systems of interest (i.e. SiC/2124 and SiC/6061). These particles, identified through X-ray analysis as: Al₂CuMg, Al₂₀Mn₃Cu₂, and FeCuMnAl₆, definitely influence fracture toughness since they generally are brittle and form in critical locations, such as along whisker-matrix interfaces and along grain boundaries. These particles are also found to form in areas where whiskers are

in contact.

Minimizing these detrimental particles is a first step toward improved fracture toughness. Improved extrusion and rolling methods developed at Advanced Composite Materials Corporation have greatly improved whisker distribution throughout the matrix. With better whisker distribution, the probability of precipitate formation at whisker-whisker contact areas is greatly decreased. In addition to minimizing precipitate formation sites, matrix alloy chemistry has been altered to reduce the amount of elements present (i.e. Fe, Mn, Mg, Cu), which are the major components of these constituent particles.

One of the more important products produced by ACMC from $\mathrm{SiC}_{\mathbf{w}}/\mathrm{Al}$ composites has been the rolled sheet. The response of the material to secondary processing and thermo-mechanical treatment is of utmost importance with respect to material quality. The present study emphasizes microstructural-mechanical property characterization of the rolled material.

SECTION II RESULTS AND DISCUSSION

EFFECTS OF HOT ROLLING ON AL2124 15% SiCW COMPOSITES

Harris and Wawner (1) noted in an earlier paper that when an Al2124 composite with SiC reinforcement was hot rolled it lost some of its strength. When this composite was subsequently heat treated in the T6 condition its strength was substantially increased. (Note: the T6 condition consists of holding the material at 500°C for 1 hour, CWC, and aged at 150°C for 8 hours.) Experiments seemed to show that the strength decrease was a result of interfacial damage which may have occurred during the rolling step. The subsequent heat treatment was noted to heal this interfacial damage, thus restoring the strength.

It has been confirmed in this study that hot rolling does indeed weaken the Al2124-SiC composite, and that a subsequent T6 heat treatment does restore the strength. The following table is the results of room temperature tensile tests performed under different conditions.

Ultimate Tensile Strength Rolled Al2124-15% SiCw Room Temperature

	Ţ	JTS .
Condition	(MPa)	(Ksi)
As Received Transverse	353	51.2
T6 Transverse	557	80.8
As Received Longitudinal	447	64.8
T6 Longitudinal	678	98.3

It is seen that in both the transverse and the longitudinal directions the strength is increased by about 55% after the heat treatment, which is a significant amount. Also, the fact that the strength is increased by almost the same transverse and percentage in both the longitudinal directions seems to suggest that interfacial damage may not be the main cause of the strength loss in this system. Healing of the interfaces would result in more of a one dimensional effect. Thus, one would expect a in the longitudinal direction. strength Instead, this data seems to imply a homogeneous effect, which would occur with changes in the matrix.

It has been found in this study that the major cause of weakening due to hot rolling is not from interfacial damage but is instead from overaging of the matrix. The composite material is hot rolled at temperatures in excess of 300°C and is then allowed to cool in air. It is during this short cooling time that large precipitates are allowed to grow and weaken the composite.

OBSERVING AND IDENTIFYING THE PRECIPITATES

The precipitates can be seen in the AR material by polishing down and ion milling small samples material. These surfaces were then studied on the scanning electron microscope (SEM). Figures 1 and photomicrographs of AR material taken in the backscattering compositional mode (compo). The compo mode shows heavier elements with lighter contrast. The precipitates can be seen rather easily as bright clumps in the matrix, which implies that they consist of heavier elements aluminum. The precipitates are relatively large with a diameter from 3-5 µm.




Figure 1. SEM Backscattered Compositional Mode, 1000x
As Received material: Large precipitates
are shown with lighter contrast.



Figure 2. BEI Compo, 2000x, AR material: Precipitates are about 5 μm in diameter.

Figure 3 and 4 on the other hand, are photomicrographs of T6 material also taken in the compo mode. It is readily noticed that no large precipitates exist. Instead they seem to be dispersed rather evenly throughout the matrix.

Energy dispersive x-ray analysis was performed on the precipitates and it was found that they consisted of copper and aluminum (the x-ray spectrum is shown in fig 5). A semi-quantitative analysis was performed and showed the precipitates to be Θ phase Al₂Cu. (see Figure 6)

DISPERSION OF THE PRECIPITATES

Basic calculations were made for the diffusion of copper in aluminum in order to help confirm that these precipitates can be dispersed at a solutionizing temperature of 500°C in one hour's time. The activation energy and the diffusivity constant for the diffusion of Cu in Al in the temperature range 433-652°C were given in the CRC Handbook of Chemistry and Physics. as Q = 32.27 kcal/mole and D = cm²/sec, respectively.(2) Therefore, 500°C of diffusion solutionizing temperature the coefficient, D, is

$$D = D_0 \exp (Q / RT)$$

= 5.57 x $10^{-10} cm^2 / sec$

The average distance, d, that a copper atom will travel in aluminum can be expressed as

$$d = \sqrt{D * t}$$

= 1.42 x 10⁻³cm
= 14 μ m




Figure 3. BEI Compo 1000x T6 material: Precipitates are dispersed.




Figure 4. BEI Compo 1000x
T6 material: Precipitates are dispersed.

Figure 5. X-ray spectrum of a precipitate.

Figure 6. Semi-quantitative analysis.

```
SEMI-QUANTITATIVE ANALYSIS: AL2124 3FT BND AR PRECIPITATE
    NORM. K-RATIC
AL-+ 0.22327 +- 0.00162
MG-F 6.88678 +- 8.88829
CU-K 0.76219 +- 0.00583
SI-K 0.00774 +- 0.00028
                 25.88 KU 47.68 Degs
ZAF CORRECTION
No. of Iterations 5
             [2]
                               [ZAF]
                                      ATOM.X WT.X
                          [F]
                    [A]
       ۲
AL-K 0.223 0.957 2.831 0.999 2.710
                                      60.74 41.43
                                            1.73
MG-K 0.006 0.917 4.088 0.991 3.720
                                      2.86
                                      34.17 55.25
CU-K
     8.762 1.857 8.999 1.888 1.857
SI-K 0.007
            0.925 3.223 0.999 2.981 2.24
                                           1.58 *
 # - High Absorbance
```

Looking back at Figures 2 and 3, it is seen that 14µm is large with respect to the precipitate size and is about equal to the precipitate spacing. Thus, according to these calculations. the precipitates can, theoretically, dispersed with the T6 heat treatment. In fact, the diffusion will be much faster in the composite than in the matrix alone due to the high dislocation density of the composite (approximately 10^{13} m⁻²)(3). The dislocation density is much higher in the composite since there is a (10:1) difference in the thermal expansion coefficients of between that the matrix and reinforcement. Many more dislocations may also be created due to work hardening which may take place during the rolling step. It is these dislocations which create high Therefore, one would expect the speed diffusion paths. precipitates to be dispersed in less than an hour's time.

In order to get an idea of the speed of diffusion, AR material was solutionized at 500°C for different periods of time. This material was then tensile tested after 24 hours of aging at room temperature. Figure 7 is the graph of strength vs. solutionizing time. It is readily seen that it takes only about 3 minutes to disperse the precipitates and restore the strength of the material! Obviously the high density of dislocations in the rolled Al2124-SiCw composite act to greatly speed up the diffusion in the material.

The high speed of diffusion in the rolled Al2124-SiCw composite system also suggests that the T6 aging condition (8 hours at 150°C) may not be necessary to reach peak strength. Instead, simple room temperature aging was investigated. Samples were solutionized and allowed to room temperature age for different periods of time before being

(MPa) 600 200 UTS vs. SOLUTIONIZING TIME Rolled AL2124 15% SiCw Samples were solutionized at 500 degrees celcius, CWC, and then room temperature aged for 24 hours. (ksi) 5 50-80 06 STRENGTH

tested. Figure 8 shows the results of this experiment. It can be seen that after only 7 hours of room temperature aging the strength has increased to within 2% of the peak strength. Thus the artificial aging at 150°C is not necessary for this composite system.


GROWTH OF PRECIPITATES UPON COOLING

In order to show that the precipitates grow as the material cools down after hot rolling the following experiment was performed: The AR material was solutionized at 500° C for two hours to ensure full dispersion of the precipitates. The samples were then allowed to cool rather steadily from 500° C to 150° C for different periods of time. At least three tensile tests were done for each condition.


Figure 9 is a plot of ultimate tensile strength vs. cooling time. The error bars show the range of strengths received and when none are shown the scatter is smaller than the point marker. It is apparent that the strength of the material drops off rather steeply with cooling time and then seems to converge to a minimum strength. At a cooling time of just 11 minutes the strength has dropped from 687 MPa (99.7 ksi) down to 456 MPa (66.2 ksi). If the material is allowed to cool for 1 hour the strength drops to 445 MPa (64.5 ksi) which is essentially the same as the AR strength of 441 MPa (63.9 ksi).

This observation alone suggests that interfacial damage is not a significant factor in the decline of strength after hot rolling in the Al2124-SiC system. Any interfacial damage would have healed during the solutionizing step, and the following cooling time would not have an adverse effect on the strength. Therefore, the strength would not drop all the way down to the AR strength upon slow cooling if interfacial damage and healing were involved.

Fig. 8







It was observed on the SEM that indeed the precipitates did grow back as the material cooled slowly. Figures 10, 11, 12 and 13 are compo photomicrographs of material that had been cooled for 5, 11, 22, and 60 minutes, respectively. One can see that the precipitates started out rather small and continued to grow larger. However, even the smaller precipitates caused the material to weaken substantially.

DETRIMENTAL EFFECTS OF LARGE PRECIPITATES

The next step is to show how the precipitates in the matrix actually weaken the composite. It is believed that there are three basic mechanisms in which weakening occurs. The growth of large precipitates tend to lower the shear strength of the matrix and they also tend to provide low energy crack paths or crack initiation sites. In addition, the precipitates tend to nucleate near whisker interfaces eventually covering the whisker and making it unable to carry much load.

LOWERING OF THE MATRIX SHEAR STRENGTH

When the precipitation hardenable matrix is grossly overaged, as in this case, only large precipitates exist and most of the copper is incorporated in these. Therefore, there is very little copper left to form the small, closely spaced precipitates needed to help prevent slip. Thus one is left with an almost pure aluminum matrix which is quite ductile and has a relatively low shear strength. However, when the composite material is solutionized and slightly aged, many small, closely spaced, precipitates form and dislocation motion, thus slip, is made more difficult. The matrix shear strength, therefore, would be greater in the T6 material.




Figure 10. Compo 2000x Cooled in 5 minutes.



Figure 12. Compo 2000x Cooled in 22 minutes.



Figure 11. Compo 2000x Cooled in 11 minutes.



Figure 13. Compo 2000x Cooled in 60 minutes.

Blanking shear tests were performed at room temperature on the material in order to compare the matrix shear strengths under the different conditions. These results could further be compared to blanking shear data for Al2024 and Al1100 which were given in the Mechanical Testing volume of the Metals Handbook (4). The room temperature results of the blanking shear tests are given in the following table.

BLANKING SHEAR DATA Room Temperature

Material	Sh (MPa)	near Strength (ksi)
A12124 15% SiCw AF		26.3
Al2124 15% SiCw T6	313	46.3
A12014 T6	284	41.2
All100 (commercial)	y pure) 66	9.6

Note: These were the average of four punch tests of which the largest scatter was only 1.1 ksi.

It is noticed that the composite T6 material shows a higher shear strength than the T6 Al2014 alloy. This observation is probably due to the SiC whiskers themselves acting as barriers to dislocations which would tend to increase the shear strength. But most apparent is the dramatic effect the heat treatment has on the shear strength of the composite material. The shear strength of the T6 material is almost double that of the AR material.

The matrix shear strength is a very important factor in the strength of a composite, since it is the shear strength of the matrix that determines how well the matrix can transfer load to the reinforcement, assuming a strong interface. The critical length to diameter ratio for a reinforcing fiber is

$$\frac{1}{d} = \frac{\sigma_{\text{fmax}}}{2\tau_{\text{my}}}$$

where σ_{fmax} is the maximum strength of the fiber and τ_{my} is the matrix shear strength (5). It is apparent that a higher matrix shear strength would mean that shorter fibers could carry more load, which would result in a stronger composite as is observed.

The difference in shear strengths of the AR and the T6 materials can also be seen by examining the fracture surfaces of samples that have been tensile tested in the longitudinal direction at room temperature. Figure 14 is the AR fracture surface which shows definite signs of low shear strength. The matrix appears to have been stretched and long whiskers have been pulled out of the surface. Figure 15, on the other hand, is the fracture surface of the T6 material, in which case evidence of high shear strength is shown. The microvoids are small with only short whisker ends inside them.

PRECIPITATES FORM CRACK INITIATION SITES AND PROVIDE LOW ENERGY CRACK PATHS

The other way in which the precipitates weaken the material is by creating large voids in the material which can then act as crack initiation sites or provide a low energy crack path. The Al₂Cu precipitates are very brittle and weak and thus either the matrix plastically flows near stress concentration sites at the interface thus causing a large void at the interface or they simply fracture causing a large void between the halves. These interfacial voids and fractured precipitates can be seen very clearly in a




Figure 14. SEM, SEI, 3000x, As Received, Room
Temperature fracture surface: Shows
low shear and whisker pullout.




Figure 15. SEM, SEI, 3000x, T6, RT fracture surface: Microvoids are small with only whisker ends showing inside them.

compo mode photomicrograph of the cross section of AR material that had been tensile tested at room temperature (see Figure 16 and 17). Figure 18 shows a crack which is growing from a void in the AR material. Therefore, when stress is applied to this composite material large voids form near the precipitates and can form a crack. This crack can then easily grow by connecting the large voids resulting in fracture of the composite.


In order to observe the crack path, simple three point bend tests were performed. Unrounded tensile bars were cut to a length of 3 cm and two notches were cut 1 cm apart. This sample was set up as shown in Figure 19. The instron was used to slowly apply a force (0.005 cm/min) to the center of the sample. When a crack was observed to form at one of the notches, the instron was stopped and the sample removed. The cross section was then polished, ion milled, and studied on the SEM. The crack in the AR material can be seen to advance through the broken precipitates, as can be seen in Figures 20 and 21. It can be seen in Figure 22 that as the crack grows the stress field ahead of it tends to fracture more precipitates, thus further lengthening the crack.


In the T6 material, however, there are no large precipitates and thus the crack tip must instead advance through the much smaller voids at the ends of whiskers, as can be seen in Figures 23 and 24. This difference makes for a much stronger composite material.

The three point bend can also be carried out to fracture in order to study the fracture surfaces. These surfaces also show how the crack propagates. In the AR material many precipitates can be seen in the voids on the



Figure 16.
Compo 2000x:
Fractured precip.
and voids by their
side.









Figure 18.

Compo 2000x:

Crack growing from fractured precip.

Figure 19.
3 POINT BEND SETUP






Figure 20.

SEI-Compo 1500x:


3 Pt. Bend crack

advancing from top

through broken

precipitates.

Figure 21.
Compo 2000x:
Crack being diverted
to the right through
broken precipitates.






Figure 22.
SEI-Compo 2000x:
Stress field ahead
of crack fractures
precipitates.




Figure 23.
SEI-Compo 2000x:

Crack advancing from top through voids at ends of whiskers. Precipitates are dispersed, except for some very small ones.



Figure 24. SEI 6000x:

Higher magnification of crack passing through whisker voids.

fracture surface as is shown in Figure 25. However, in the T6 material only whisker ends can be seen in the microvoids (see Figure 26).

NUCLEATION OF AlgCu NEAR THE WHISKER INTERFACE

The third way in which the precipitates weaken the composite is by nucleating at either the whisker interface or at dislocations near the interface. In order to observe the nucleation of the precipitates the cross sections of the samples that have been slowly cooled from the solutionizing temperature were studied. In these samples the precipitates were smaller and in their beginning stages of growth. Nearly all the precipitates are observed to be growing near a whisker interface, as can be seen in Figure 27. precipitate grows it begins to cover the interface of the whisker until the whisker is completely enveloped, as can be The cross section of an AR sample seen in Figure 28. observed parallel to the whiskers shows the advanced stages of precipitate growth very well (see Figure 29). see that the precipitates not only envelope one whisker, but they each tend to cover several whiskers.

When the whiskers are engulfed in brittle Al₂Cu they are unable to carry much load for two reasons. First of all, there appears to be no interfacial bonding between the whiskers and the Al₂Cu. Secondly, even if an interfacial bond did exist very little load could be transferred because the whisker and the Al₂Cu are both brittle materials. In fact many precipitates with whiskers pulled out of them were noticed on the fracture surfaces. Figure 30 shows a good example of how the whiskers simply pull out of the precipitates and are thus unable to help strengthen the material.




Figure 25.
SEI 2000x AR material:

3 Pt. Bend fracture surface with many precipitates exposed.




Figure 26.

SEI 3000x T6 material:

3 Pt. Bend fracture surface showing small voids with whisker ends in them. No precipitates can be seen.

One question left unanswered is, do the precipitates nucleate at the interface or at dislocations near the interface? The answer can be found by studying the extruded Al2124 20% SiCw composite on the SEM. Figure 31 and 32 are compo photomicrographs of this material. It is apparent that the precipitates seem to grow in linear groups along the extruded direction. From the photomicrographs one can that the whiskers are distributed rather evenly see throughout the material even though the precipitates are This would tend to imply that the the precipitates are growing at dislocations and that some areas of the extruded material have higher dislocation densities than others. Some areas probably have higher dislocation densities due to an uneven distribution of stresses which occurs during the extrusion process. Thus, plastic deformation would be uneven in the extruded composite.

GROWTH OF PRECIPITATES

The rate of precipitate growth should reach a maximum at some temperature. In order to find this temperature DSC (Differential Scanning Calorimeter) experiments performed. Figure 33 shows the results of DSC analysis performed on material that had been solutionized. noticed that the precipitates seem to be growing fastest at a temperature of about 250°C for the following reason: According to the phase diagram for copper in aluminum, at 4 wt. % Cu the aluminum is supersaturated with copper up to a temperature of about 500°C, see Figure 34 (6). Therefore, it is energetically favorable for theta phase precipitates to form at temperatures below 500°C, and thus energy is released upon their formation (exotherm). This energy then goes to heat the material. Therefore, when the precipitates

Figure 30.
SEI 10000x:
Large precipitate
with whiskers
pulled out of it.






Figure 31.
Compo 120x
Extruded material:
Precipitates are
growing in linear
bunches along ext
direction.

Figure 32.

Compo 480x:

Whiskers are distributed rather evenly in the extruded material even though the precipitates are not.



Figure 33. Differential Scanning Calorimetry (DSC) results for solutionized rolled Al2124 15% SiCw.





Figure 34. Phase diagram for the aluminum-copper system. The pure θ phase contains about 46 wt.% Cu at room temperature and corresponds to CuAl₂ (6).




are growing fastest it should require a minimum amount of heat per gram to raise the temperature at a fixed rate. From the DSC graphs it can be seen that there is a minimum heat per gram at a temperature of 250°C, which implies the precipitates are nucleating and growing fastest at this temperature.


EFFECTS OF HIGH TEMPERATURE ON Al 2124-Sicw COMPOSITES

Figure 35, displays the general trend of aluminum composites at elevated temperatures. It is apparent that the strength of these composites drops off sharply at temperatures over 300°C. This observation raised the question as to what is the controlling mechanism for failure at these higher temperatures and if the aluminum 2124/SiCw composites displayed similar behavior. Hence, the second goal of this research was to define the mechanical response and fracture characteristics of Al2124/SiCw composites at elevated temperatures and how they are related to the microstructure.

EFFECTS OF TEMPERATURE ON THE STRENGTH

Figure 36 shows the results of the Al2124/SiCw tensile tests. Before these tests were performed the sample was allowed to heat up to the desired temperature (about 15 minutes) and then were held at that temperature for at least 15 minutes to ensure equilibrium. Also included in this graph is data for extruded Al 1100/20 v/o SiCw. It can be seen that the Al2124-SiC composite seems to hold its strength to slightly higher temperatures than the composites in Figure 35. The strength did not drop sharply until a temperature of 300°C was reached. It is also noticed that the precipitation hardened alloy composite had a much higher







commercially pure aluminum than the composite at temperatures up to 350°C. At temperatures over if the precipitates offer it appears as contribution to the strength of the composite, as one would expect since the precipitates are solutionized and offer no barrier to slip. In fact the orientation reinforcement itself does not seem to be a factor in the strength at temperatures above 350°C. Thus implying that the reinforcement does not carry any load and does not, therefore, contribute to the strength at such temperatures.

Figure 37 shows data for extruded Al2124/20 v/o SiCw that has undergone a T6 heat treatment and for unreinforced extruded Al2124 also with a T6 heat treatment. In this case, the SiC whisker reinforcement gives a much stronger material up to a temperature of 300°C. However, above this temperature the strengths are nearly identical, again implying that the whiskers basically carry no load at temperatures at and above 300°C. It is also noticed that the hot rolled material seems to maintain its strength a little better at higher temperatures, possibly due to the higher dislocation density of the rolled material due to work hardening. The dislocations themselves would help prevent slip and give the matrix a greater shear strength at higher temperatures.

It is rather obvious that the strengths of the aluminum composites drop off at higher temperatures simply due to a loss in shear strength of the matrix. It can be seen from a graph of shear strength vs. temperature (Figure 38) that the shear strength drops off rather quickly with an increase in temperature. At temperatures over 200°C the shear strength of the T6 and the AR material both fall to nearly identical





values. Recall that the UTS of the T6 transverse material did not drop off sharply until a temperature of 250°C was reached. Therefore, the shear strength should not be expected to drop off in the T6 material until a temperature of 250°C is also reached. Thus, there appears to be a discrepancy between the behavior of the UTS and the shear data. However, one must keep in mind that the shear samples were heated much more slowly and were held at the desired temperature longer than the tensile tested samples. Thus, the precipitates were allowed to form for a longer time which would result in the lower temperature drop of the shear strength that is observed.

Lowering of the shear strength at higher temperatures can also be distinguished by studying whisker void sizes at the different temperatures. Figures 39, 40 and 41 are photomicrographs of cross sections of rolled 2124 near the fracture surface of tensile tested specimens. temperature the voids at the whisker ends are very small and in their beginning stages. In fact they are starting at the stress concentration sites at the edges of the whiskers as is shown in a paper by Nutt (7). However when the temperature is raised to 450°C the voids become much larger and are at times as long as the length of the whisker itself. The shear strength of the matrix is so low that the whiskers are literally pulled through the matrix contribute nearly nothing to the strength.

EFFECTS OF TEMPERATURE ON DUCTILITY

Some rather interesting phenomena happen to the ductility of the rolled aluminum matrix composite at elevated temperatures. Figure 42 and 43 are graphs of strain vs. temperature for the rolled material tensile

Figure 39.
SEI 2600x
T6 material
tensile tested
at room temp.
Voids are small.






Figure 40.
SEI 10000x:
T6 material
tensile tested
at RT. Voids are
starting at the
edges of whiskers

Figure 41.
SEI 2000x:
T6 material
tested at 450°C.
Voids are very long.






Figure 42.





tested in the longitudinal and transverse directions. The first thing to notice is that the strain in the transverse direction is generally much higher than that in the longitudinal direction, as one would expect since the whiskers constrain the material much more in the longitudinal direction. However, at a temperature of 450°C the whiskers no longer constrain the matrix thus the strain is the same for both the AR and the T6 material in both the transverse and longitudinal directions.

At room temperature it is believed that the AR material is less ductile simply because the large precipitates act as crack initiation sites, thus very little plastic deformation is allowed to occur before fracture. The lack of plastic deformation can readily be seen either by observing the room temperature stress strain curves for the AR and the T6 material in Figures 44 and 45, or by looking at the Yield Strength vs. Temperature graph in Figure 46. One can see that the room temperature yield strengths are the same even though the ultimate strength of the T6 material is 55% higher than that of the AR material. Thus very little plastic strain takes place in the AR material before fracture.

In the T6 material, as the temperature is increased the material becomes less ductile and reaches a minimum strain at 300°C. It is believed that this minimum is due to a nucleation and growth of larger precipitates which would again act as crack initiators and decrease the plastic deformation, thus decreasing the strain. This decrease in plastic deformation is made obvious by comparing the number of voids created at the ends of whiskers in the material tested at the different temperatures. Figures 47, 48 and 49 are photomicrographs of general areas in samples tested at

Figure 44.

Room temperature stress-strain curve for AR material: Very little plastic flow.





Figure 45.

Room temperature stress-strain curve for T6 material: Much more plastic flow.






Figure 47.
SEI 1000x:
T6 material
tested at 250°C.
Very many voids.





Figure 48.
SEI 1000x:
T6 material
tested at 300°C.
Few voids.

Figure 49.
SEI 1000x:
T6 material
tested at 350°C.
Many voids again.



250, 300, and 350 degrees celsius, respectively. It is clear that there are very few whisker voids in the material tested at 300°C compared to the others. A count gave 98 and 127 voids in the material tested at 250°C and 350°C, respectively. However the material tested at 300°C only had 33 voids. Thus, plastic flow is at a minimum at 300°C in the T6 material.

The strain of the AR material, on the other hand, increases to a maximum at about 350°C. This increase in strain is likely due to the large existing precipitates growing even larger and the matrix thus becoming even more ductile combined with the matrix becoming more ductile with increase in temperature alone. This increase ductility also corresponds to a minimum in yield strength, as can be seen in Figure 46. The large precipitates do not initiate cracks as readily when the matrix is more ductile, simply because the yield strength is much less, which in increases the fracture toughness. The decreases again as the temperature is raised to 450°C possibly because this high temperature solutionizes the precipitates thus resulting in some solid solution strengthening which makes the matrix less ductile.

The degree of necking of the tensile specimens also represents the ductility of the composite. Figures 50 and 51 are the graphs of necking vs temperature for transverse and longitudinal tensile tests. As one would expect after studying the strain data, the necking was generally less in the longitudinal samples. Also the T6 samples tend to resist the necking to higher temperatures.

Thus the precipitation hardenable matrix not only has a large effect on the strength of the composite but it also has a large effect on the ductility. Not only does heat

Figure 50.





Figure 51.



treating the rolled material strengthen it, but it also increases its ductility at room temperature.

SECTION III CONCLUSIONS

EFFECTS OF HOT ROLLING ON AL2124-SiCw COMPOSITES

It has been confirmed in this study that when Al2124 15% SiCw is hot rolled it loses a good portion of its strength. It has been found that this loss in strength is mainly due to overaging of the precipitation hardenable matrix. Evidence shows that large Al₂Cu precipitates grow as the material is allowed to cool down after the rolling step.

It has also been confirmed that the strength of the material can be regained by subjecting it to a T6 heat treatment (1 hour at 500°C, CWC, and aged at 150°C for 8 Experiments show that the strength is regained mainly because the heat treatment disperses However, it has been discovered that this rather long heat treatment sequence can be made much shorter due to the high dislocation density of this material. precipitates can be dispersed by solutionizing the material at 500°C for very short periods of time (as short as 1.5 minutes) followed by cold water quenching. Likewise, it has been found that only a very simple aging process is needed to obtain peak strength. Artificial aging at 150°C is not The material need only be aged at room temperature for a time of 7 hours or more. Thus industry should be able to heat treat the rolled composite material much more efficiently and inexpensively than a T6 heat treatment would permit.

WAYS IN WHICH THE PRECIPITATES WEAKEN THE COMPOSITE

It was discovered that there are three basic ways in

which the large precipitates weaken the composite.

- 1) The growth of large precipitates can weaken the material by removing the small precipitates which are needed to help prevent dislocation motion, thus slip. Therefore, the shear strength of the matrix is reduced which results in a larger critical whisker length. Thus shorter whiskers are unable to carry as much load and the material is weakened.
- 2) The large precipitates also tend to create large voids in the composite which then act as crack initiation sites and also provide low energy crack paths.
- 3) Lastly, evidence shows that the precipitates tend to nucleate at dislocations near the interface. Therefore, the precipitates tend to grow around the whiskers and envelope them, thus rendering the strengthening effect of the whiskers useless.

HIGH TEMPERATURE FRACTURE

It was shown that the Al2124 matrix provided a much stronger composite than a pure aluminum matrix, at least up to a temperature of 400°C. At temperatures higher than this it appears as if precipitation strengthening offers no contribution to the strength. It has also been shown that the reinforcement itself offers no contribution to the strength at temperatures above 300°C, due to very low shear strengths in the matrix at these high temperatures. Through elevated temperature shear tests it was shown that the main reason for the drop in strength at higher temperatures was due to a rapid decrease in shear strength of the matrix.

HIGH TEMPERATURE DUCTILITY

It was found that the strain in the transverse direction was much larger than that in the longitudinal direction. It was also found that not only does the T6 heat

treatment increase the strength of the rolled composite but it also increases the room temperature ductility. material has very poor ductility because the large initiate cracks. which precipitates lead to tensile fracture, before much plastic deformation can take place. However, the ductility of the AR material increases with temperature to a maximum near 350°C, while the ductility of the T6 material decreases to a minimum at a temperature of 300°C. The precipitates are also thought to be responsible for these effects.

OTHER OBSERVATIONS

It was also observed using Differential Scanning Calorimetry that the precipitates seem to nucleate and grow fastest at a temperature of 250° C.

The extruded Al2124 15% SiCw composite was much less homogeneous than the hot rolled material. Precipitates were observed to grow in linear groups along the extruded direction apparently due to variations in plastic deformation.

The rolled T6 material resisted necking to higher temperatures than the AR material. The AR material began to neck significantly at 250°C while the T6 material resisted the necking until a temperature of 300°C was reached.

SECTION IV FUTURE RESEARCH

From this research, it is obvious that the matrix plays a crucial role in the properties of a composite, both at high and low temperatures. The shear strength in particular is very important since it is the main factor in how much load the whiskers will carry. One can see that a precipitation hardenable matrix such as Al 2124 does make a very good matrix at temperatures below 200°C, however, it does not make a very good matrix at high temperatures since the copper precipitates out and leaves behind almost pure aluminum which has a low shear strength.

It is believed that in order to make a strong high temperature aluminum matrix composite one should dispersoid hardening rather than precipitation hardening. The dispersoids should be very small (.01 - .1 μm) and insoluble at high temperatures. They should also have an incoherent interface so that dislocations will be forced to bypass them. A suggestion for these dispersoids might be ground up SiC particles, since these would satisfy the above requirements. These dispersoids would then work harden the matrix even at high temperatures (although not by as much since dislocations can bypass particles faster at high The dispersoids would probably strengthen temperatures). the composite at higher temperatures, however, the problems of low ductility and fracture toughness would probably still exist.

REFERENCES

- C. R. Harris and F. E. Wawner, "Damage and Repair of the interfacial Region in Silicon Carbide Whisker Reinforced Aluminum Composites", To be published in <u>Powder Metallurgy Composites</u>, The Metallurgical Society, 1988.
- 2. CRC Handbook of Chemistry and Physics, 1986-1987, 67th edition, RC Press Inc., Boca Raton, Fl, p. F-46.
- M. Vogelsang, R.J. Arsenault, and R.M. Fisher, "An in-Situ HVEM Study of Dislocation Generation at Al/SiC interfaces in Metal Matrix Composites", Metallurgical Transactions A, Vol. 17A, p. 387, March, 1987.
- 4. <u>Metals Handbook</u>, 9th edition, Vol. 8: Mechanical Testing, American Society for Metals, Metals Park, Ohio,p.64, 1985.
- 5. A. Kelly and G. J. Davies, "The Principles of the Fiber Reinforcement of Metals", Metallurgical Reviews, vol. 10, No. 37, p. 25, 1965.
- A. L. Ruoff, <u>Materials Science</u>, Prentice Hall, Inc., Englewood Cliffs, New Jersey, p. 360, 1973.
- 7. S. R. Nutt, "Interfaces and Failure Mechanisms in Al-SiC Composites", <u>Interfaces in Metal Matrix Composites</u>, The Metallurgical Society Inc., p. 157-167, 1986.

PUBLICATIONS AND PRESENTATIONS

A. PUBLICATIONS

- C. R. Harris and F. Wawner, "Tensile Strength-Microstructure Correlations in Silicon Carbide/Aluminum Composites," Processing and Properties for Powder Metallurgy Composites, Edited by P. Kumar, K. Vedula and A. Ritter, the Metallurgical Society, 1988, pp. 107-116.
- F. Wawner, "Boron and Silicon Carbide/Carbon Fibers," in <u>Fibre Reinforcements for Composite Materials</u>, A. R. Bunsel, editor, Elsevier, Amsterdam, Chapter 8 (1988), pp.371-426.

Accepted for Publication

F. E. Wawner and J. W. McCoy, "The Origin of the 'Crack Tip' Mode of Failure in Boron Filaments," Accepted for publication in Journal of Materials Science (1988).

Submitted for Publication

F. E. Wawner, "Discontinuously Reinforced Metal Matrix Composites: Microstructure and Mechanical Property Correlations," Invited Contribution to the <u>Encyclopedia of Composites</u>, Edited by S. M. Lee, VCH Publishers, New York, 1988.

To Be Submitted

- R. Schueller and F. Wawner, "An Analysis of High Temperature Behavior of Discontinuously Reinforced Al Alloys," To Scripta Met.
- R. Schueller and F. Wawner, "An Analysis of the Effects of Hot Rolling on Discontinuously Reinforced Al Alloys," To Met. Trans. A.

B. PRESENTATIONS

- R. Schueller and F. Wawner, "An Analysis of High Temperature Behavior of Discontinuously Reinforced Al Alloys," Presented at the 10th Annual Dicontinuous Reinforced Metals Working Group Meeting, Park City, UT, Jan. 4-8, 1988; Published in Preceedings.
- R. Schueller and F. Wawner, "An Analysis of the Effects of Hot Rolling on Discontinuously Reinforced Al Alloys," Presented at the 66th Annual Meeting of the Virginia Academy of Science (University of Virginia, Charlottesville, VA, May 25-27, 1988).

DISTRIBUTION LIST

Copy No.	
1	Dr. Steven Fishman Non-Metallic Materials Code 1131N Office of Naval Research 800 N. Quincy Street Arlington, VA 22217-5000
2 - 7	Director Naval Research Laboratory Washington, DC 20375
	Attention: Code 2627
8 - 19	Defense Technical Information Center, S47031 Bldg. 5, Cameron Station Alexandria, VA 22314
20 - 31	Dr. F. E. Wawner, MS
32	Dr. T. H. Courtney, MS
33 - 34	Ms. E. H. Pancake, Clark Hall
35	SEAS Publications Files
*	Office of Naval Research Resident Representative 818 Connecticut Ave., N.W. Eighth Floor Washington, DC 20006 Attention: Mr. Michael McCracken Administrative Contracting Officer

*Send Cover Letter Only

2055:a1d:DW213R

UNIVERSITY OF VIRGINIA School of Engineering and Applied Science

The University of Virginia's School of Engineering and Applied Science has an undergraduate enrollment of approximately 1,500 students with a graduate enrollment of approximately 560. There are 150 faculty members, a majority of whom conduct research in addition to teaching.

Research is a vital part of the educational program and interests parallel academic specialties. These range from the classical engineering disciplines of Chemical, Civil, Electrical, and Mechanical and Aerospace to newer, more specialized fields of Biomedical Engineering, Systems Engineering, Materials Science, Nuclear Engineering and Engineering Physics, Applied Mathematics and Computer Science. Within these disciplines there are well equipped laboratories for conducting highly specialized research. All departments offer the doctorate; Biomedical and Materials Science grant only graduate degrees. In addition, courses in the humanities are offered within the School.

The University of Virginia (which includes approximately 2,000 faculty and a total of full-time student enrollment of about 16,400), also offers professional degrees under the schools of Architecture, Law, Medicine, Nursing, Commerce, Business Administration, and Education. In addition, the College of Arts and Sciences houses departments of Mathematics, Physics, Chemistry and others relevant to the engineering research program. The School of Engineering and Applied Science is an integral part of this University community which provides opportunities for interdisciplinary work in pursuit of the basic goals of education, research, and public service.